

# VEHICLE ASSESSMENT REPORT

REGO NO. XQL684

Salvage Advice 960920

LOT 14

\*\* THIS REPORT IS INTENDED AS A GUIDE ONLY TO BUYERS \*\*

**NO WARRANTY OR GUARANTEE WHATSOEVER IS GIVEN REGARDING THIS VEHICLE**

(Vehicles may be covered by the manufacturers warranty)

**MODEL 11/06 COMMODORE VE OMEGA SEDAN 3.6L KMS 58446**

THE FOLLOWING SYMBOLS INDICATE ITEMS CHECKED AND SEVERITY OF FAULTS							
M MINOR ADJUSTMENT AND OR REPAIR		E EARLY ATTENTION DESIRABLE			U URGENT ATTENTION ESSENTIAL		
SYSTEM/COMPONENT		COMMENTS - IF NECESSARY					
ENGINE PERFORMANCE	OK	GOOD					
GEARBOX	OK	T BAR AUTO					
DIFFERENTIAL	OK						
BRAKES FOOT/PARK	OK						
EXTERNAL LIGHTS	OK						
STEERING/SUSPENSION	OK						
ALTERNATOR/BATTERY	OK						
Tyres (Minimum tread depth measurement in mm)	OK	RF 8	LF 8	RR 7	LR 6	Spare 1 5	Spare 2
Tyres are legally serviceable when tread is visible across the full face of the tyre – Tread depth measurement is an indicator of service life remaining							
<b>BODY: Inspection of the Body is the sole responsibility of the purchaser.</b>							
OTHER							
EXTRAS	SERVICE & OWNERS BOOKS, KEYS 2, DUAL AIRBAGS, ABS, TRACTION CONTROL, DUAL FUEL, CRUISE CONTROL, POWER WINDOWS, TOW BAR						
AIR CONDITIONER				POWER STEERING			

**CONDITION OF VEHICLE (AVE = Condition expected for the age of the vehicle)**

The Mechanical Condition of vehicle is based on a road test of the vehicle up to 50kph

MECHANICAL			BODY / TRIM			KILOMETERS FOR AGE		
BELOW	AVE	GOOD	BELOW	AVE	GOOD	HIGH	AVE	LOW
		X		X			X	

Purchaser's name \_\_\_\_\_

Address \_\_\_\_\_

Post code \_\_\_\_\_ Phone \_\_\_\_\_

**REFERENCE: DMF**